

NOTES & ERRATA FOR PROJECTS PUBLISHED IN SILICON CHIP (2025)

Please note: errata apply primarily to the print edition of SILICON CHIP as online issues are normally changed when an error is identified. However some errata may still apply to the online edition; check carefully before making any changes to a project.

Pico/2/Computer, April 2025: boards with CH334F chips marked 13122E20 will not work unless resistors R54 and R55 are removed. Boards we sell with matching chips will come with those resistors removed so they function correctly. CH334F chips with batch code 1163FD43 are not affected and will work with the resistors in place. (05/25)