

## NOTES & ERRATA FOR PROJECTS PUBLISHED IN SILICON CHIP (2026)

*Please note: errata apply primarily to the print edition of SILICON CHIP as online issues are normally changed when an error is identified. However some errata may still apply to the online edition; check carefully before making any changes to a project.*

**Scale Speed Checker for model railway, January 2026:** the 120Ω resistors should be in series with pin 2 of the connectors for the IR sensors (and the photodiodes), not pin 1 (the collectors). Also, the IR LED anodes and cathodes should be swapped. (03/26)